Shop Name: Precision Auto Source
Tel: 9047012621
Email: sales@precisionautosource.com
Address: 11631 Columbia park Dr e

Report ID: REDACTED
Test Time: 2026-08-05 18:19:10
Technician: --

2010 Lexus VEHICLE DIAGNOSTIC REPORT

Vehicle Information

2010/Lexus/ES350/2GRFE
VIN: REDACTED
Odometer Reading: 122040km
License Plate: --

Customer Information

Name: --
Tel: --

Device information

Scanner: MaxiCOM MK808
Version: V11.70
Serial Number: REDACTED
Repair Order Number: --

System Scanned (26)

System	Status/DTC
Engine	4
Electronically controlled transmission (ECT)	0
ABS/VSC/TRC	1
SRS airbag	0
Combination meter	0
Tire pressure monitor	5
Main body	4
Mirror	0
Driver door motor	0
Sliding roof	0
Driver seat	0
Right rear door motor	0
Left rear door motor	0
Passenger door motor	0
Air conditioner	2
Gateway	0
Master switch	0
Tilt & telescopic steering	0
E-ACM	0
Cruise control	0

Intuitive parking assist	0
Adaptive front-lighting system (AFS)	4
Smart access	0
Navigation system	1
Telematics	3
Occupant detection	0

DTC (24)

Engine (4 DTCs)

DTC	Description	Status
P1604	Startability fault	Current
B2799	Engine immobilizer system	Current
P1604	Startability fault	History
B2799	Engine immobilizer system	History

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1246	Master cylinder pressure sensor	Current

Tire pressure monitor (5 DTCs)

DTC	Description	Status
C2121	Data from transmitter ID 1 not received (main)	Current
C2122	Data from transmitter ID 2 not received (main)	Current
C2123	Data from transmitter ID 3 not received (main)	Current
C2125	Data from transmitter ID 5 not received (main)	Current
C2142	Transmitter ID 2	Current

Main body (4 DTCs)

DTC	Description	Status
B1206	Power window(P/W) master switch electronic control unit(ECU) communication stop	History
B1276	Lost communication with air conditioner and meter electronic control unit(ECU) or mirror electronic control unit(ECU)	History
B2281	P signal	History
B2321	Driver door motor electronic control unit(ECU) communication stop	History

Air conditioner (2 DTCs)

DTC	Description	Status
B1421	Passenger solar sensor circuit	Current
B1424	Driver solar sensor circuit	Current

Adaptive front-lighting system (AFS) (4 DTCs)

DTC	Description	Status
B2412	Left headlamp swivel motor	History
B2413	Right headlamp swivel motor	History
B2417	Left headlamp beam level control motor	History
B2418	Right headlamp beam level control motor	History

Navigation system (1 DTC)

DTC	Description	Status
B15E1	Media fault	History

Telematics (3 DTCs)

DTC	Description	Status
B15EC	Replace back up battery	Current
B15C4	Supplemental restraint system(SRS) communication error	History
B15EC	Replace back up battery	History

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.